FORM F - STRUCTURE

MASSACHUSETTS HISTORICAL COMMISSION Office of the Secretary, State House, Boston

In Area no.	Form no.
	27

And the second s	

4. Map. Draw sketch of structure location in relation to nearest cross streets, buildings, other structures, natural features. Indicate north.

À	1 /			North
	1 4//	1		Employee
	- /A			Home V
48	27-			1/ 1
Service and	// #			
Vaintenanc			-	//N
Ruildings			-	61
Juliunus			1	
1/ 3/)
118				
			Ma Ma	
	// `	21	Com	piex
> %			5 //	13
				10
Ň /			South	Y
Λ	/ Water	Eπ	noioyee's	//
	Attendant's		tome))
'X 11-11-1				
			Nurses	3
Blag.		-1 1	Home	. 11
	1/3	TO Hous	\ \\	1 11
13//2	Time S	+11/1==	io's	<i>\</i>
1 - 1	St.	3	¥′-	
1 8 BARCH	900	-	Prince St	
10	E PTI		31	

DO NOT USGS Qua		IN	THIS	SPACE
MHC Pho	to no			

1	2		Northampton	
		ress Hospital Hill		
	*	(Northside Prince Street)		
	ne <u>Paint Shop</u>			
		sent use	storage	
7 <u>-</u>	, — —	sent own	ner Comm. of Mass.	
4.0				
		e of stru	acture (check one)	
		lge	pound	
		al	powder house	
· ref		1	street	
		•	tower	
	gat		tunnel	
	kilı	-	wall	
	ligi	nthouse	windmill	
	oth	er <u>sho</u>	P .	
5.	Des	scription		
	Dat	e	1908	
	S	Source	Annual Report	
	Con	struction	material brick	
	Din	nensions_	15' x 15' ·	
	Sett	ing in r	ear of Main Complex	
	Con	dition	good	
			•	
6.	Rec	orded by_	Ed Lonergan	
	Org	anization	Northampton Historical Commissi	
	Date	9	February, 1981	

(over)

7.	Original owner (if known)	Comm. of Mass.
	Original use	"fireproof" paint shop
	Subsequent uses (if any) and da	tes

8. Historical significance.

Fire was always a matter of concern at large institutions so it was necessary to take precautions with flammable substance. Originally the trade shops and their storage space had been in the basement of the hospital building. This was built of brick, but had wooden floors and partitions. The shops were soon moved to small out-buildings at the rear of the hospital. However, in time it was felt that a separate structure solely for the painters was the best way to prevent fire damage.

In 1905 the State Hospital trustees requested \$2500 for the construction of a "fireproof shop" for the painters. This was built in 1908 at a cost slightly in excess of \$2000. It is one-story in height, with hipped roof and finial. Brownstone is used for the sills and lintels of the tall windows.

9. Bibliography and/or references such as local histories, deeds, assessor's records, early maps, etc.

Annual Reports: 1905, 1908 Forbes Library